

Operation Description at Time of Inspection:

Universal Scrap Management, LLC
Facility is a scrap metal recycling yard with used oil and diesel tanks

Inspector Comments: (Refer to the Violations Found on This Inspection page for violations cited, if any)

Facility has a current Broward County Hazardous Materials License Exp. 02/28/2021
Facility is a scrap metal recycling yard with used oil and diesel tanks

Scrap metal piles staged throughout the facility

*Found a heavy presence of petroleum contact water throughout the facility

Facility has 1-500g double-walled Diesel above ground storage tanks,

*Tank is within a damaged/broken concrete secondary containment

*Along with several used oil drums and empty drums within that area

Facility has 1-500g single-walled Diesel above ground storage tank

*Tank needs to be in secondary containment

*Found several 55g used oil drums on site that were not placed on secondary containment

Found a 300g above ground storage tank for used oil brought in by customers.

*The used oil tank has some spills around it.

*Tank is within a damaged/broken concrete secondary containment

Toured facility with City of Lauderhill Fire Inspector Matthew Newman

*He observed that facility should cease collecting propane tanks with valve covers

*Facility must place proper NFPA Diamond on site to represent hazards on site

*The disposal manifests from not available on site for review.

Labels or stencils were provided to properly label wastes.

Brochure left on site for Pollution Prevention and Repair Facilities.

The site sketch and the site photos were reviewed in the electronic database.

No changes were made.

A Customer Service Card was not provided to operator; there is a link to the PPD Customer Survey included in the e-mail

Report to be sent to

Carlos Teran

Carlos.A.Teran@hotmail.com

Distributed Informational Brochures, if Any:

VIOLATIONS FOUND ON THIS INSPECTION

As a result of this licensing inspection, EPD staff believe that a violation of the Broward County Natural Resources Protection Code (the Code) may have occurred. Appropriate enforcement action may follow to ensure compliance with the Code. However, correcting the violation may avoid enforcement action in this matter. If you believe the information below does not constitute a violation as alleged, or if you would like to discuss methods of correcting the problem, you are encouraged to immediately contact the inspector named on the first page of this inspection.

Violations Found During this Inspection

Rule Cite*: 27-356(b)(4)a.2. **Code:** Unknown

Description of Violation:

No NFPA Diamond on site, and containers not properly label

Corrective Action Required:

Facility must place proper NFPA Diamond on site to represent hazards on site, and have all containers properly label

Rule Cite*: 27-356(b)(4)a.1. **Code:** Unknown

Description of Violation:

Found damaged/broken concrete secondary containment

Corrective Action Required:

Please make repair to damaged/broken concrete secondary containment

Rule Cite*: 27-356(b)(4)a.1. **Code:** Unknown

Description of Violation:

Found several drums, and a single wall Tank were not placed on secondary containment

Corrective Action Required:

Please place all drums, and a single wall Tank in secondary containment

Rule Cite*: 27-356(b)(4)c.10. **Code:** Unknown

Description of Violation:

*Found a heavy presence of petroleum contact water throughout the facility

Corrective Action Required:

Please have a complete clean out of the facility to removed and petroleum contant water as hazardous waste

Rule Cite*: 27-356(b)(4)d.1. Code: Unknown

Description of Violation:

no waste manifest available

Corrective Action Required:

Please submit waste manifest for all hazardous waste on site

*Chapter 27 of the Broward County Natural Resource Protection Code [Rules 62-761 or 62-762, F.A.C. or Chapter 40, Code of Federal Regulations]

Please correct this violation(s) within 30 days by taking the corrective action described above.