

# GYMDOORS FLORIDA, LLC

380 Semoran Commerce Pl C-303. Apopka FL 32703

Tel: 407-574-7366; Fax: 407-574-7367

[www.gymdoorsfl.com](http://www.gymdoorsfl.com)

[airwalls@gymdoorsfl.com](mailto:airwalls@gymdoorsfl.com)



November 17, 2019

**TO: CITY OF LAUDERHILL**

ATT: Keith Madigan:954-730-3044; [kmadigan@laudershill-fl.gov](mailto:kmadigan@laudershill-fl.gov)

**FROM:** Clement Baburam- [clement.baburam@gymdoorsfl.com](mailto:clement.baburam@gymdoorsfl.com)

**RE: BASKETBALL BACKSTOP REPAIRS @ SADKIN REC CENTER.**

The repairs to the 6 basketball backstops was completed on November 14, 2019.

Here are a few additional issues we want to make you aware of:

1. The main support structure, made up of three parallel pipes, where it is attached to the trusses' sways excessively during operation. The front pipe where the hoist is attached is bending when lifting the new heavier glass boards and height adjusters. We are recommending to strengthen and stabilize this by adding two pipes on each of the side courts. The new pipes will across the three parallel pipes, perpendicularly and clamped in place. It will tie it all together and make it more rigid. This issue is only with the side courts.
2. Because the design of the side courts, the heavier boards and added height adjusters were causing the mast not to go all the way down and latch in place. We were able to compensate for this by adding weights on the knee brace to help push the masts in place. The weights we added were pieces of metal we had on hand. We propose to replace these "Not so pretty pieces" with solid steel bar, 2 3/8 diameter x 18 inches long. These will be clamped to the knee brace to help lock the mast in place.
3. **Please note that these problems could not be noticed before since the goals did not function to go up and down.**
4. Supply one-man Genie lift to perform the above repairs.

**PROPER LABOR AND MATERIALS: -----\$4,600.00**

**Exclusions:**

- Sales Tax.



Allied Member